

PRICELIST - 2009

CYLINDER - TESTING

Hydrostatic Inspection inc Valve Service	£35
Visual Inspection inc Valve Service	£30
Paint B/W Quadrants	£10
Internal Shotblast	£10
External Shot Blast Re-Paint & Quadrants	£35
Oxygen Clean Cylinder (inc Valve)	£15
Cylinder Valve Service	£10
Cylinder Valve Supply & Fit M25 x 2 (Din convertible)	£35
Cylinder Pillar Valve G3/4 (Din Convertible)	£30
Cylinder Protective Boot	£9

REGULATOR - SERVICE

Regulator Service (Plus Parts)	£20
Typical full cost iro £49	
Regulator Alternative Air / Buddy Auto Air / Scubapro Air 2	£15

Air Fills - to 300Bar

Air Club (Air Ticket 15 Fills)	£35
Air Single Fill	£3

BCD - SERVICE

BCD Inflator Service	£10
BCD Full Service	£28
BCD Full Service (Auto Air / Air-2)	£35

DRY SUITS - REPAIR

Dry Suit Valve Service	£10
Latex Cuffs Replacement (Standard)	£30
Latex Cuffs Replacement (Heavy Duty)	£35
Latex Neck Seal Replacement	£35
Cuff & Neck seal replacement done together	£60
Replace Boots	£78
Replace Front Zip	£150
Replace Rear Zip (Standard)	£140
Replace (or fit) Convenience Zip	£75
Neoprene Neck Seal	£45
Neoprene Cuffs (Fitted)	£35
Neoprene Boots (Fitted)	£85
Pocket attached to wet suit / dry suit	£10
Pressure Test	£15
Repair Holes - from	£5